

Straight Tension Fabric Display



- Connect tubes of the frame(there are number labels on tubes)
- Wrap up the frames with the graphic from top to bottom and zip up,then put them on the metal base



Out the light clip on the top of display and fix it with screw, then connect the light and the clip